


**Compatibilities BUSing-MBAC-D
gateway**



ingenium

Compatible models always refer to indoor units, not references to outdoor plus indoor units.

Line	Indoor unit model (prefix)
Domestic	MSZ-A
	MSZ-AP
	MSZ-CGE
	MSZ-D
	MSZ-DM
	MSZ-EF
	MSZ-FA
	MSZ-FD
	MSZ-FE
	MSZ-FH
	MSZ-GA
	MFZ-KA
	MSZ-GB
	MSZ-GC
	MSZ-GE
	MSZ-GF
	MSZ-GL
	MSZ-HR
	MSZ-LN
	MSZ-SF
	MSZ-WN
	MSY-A
	MSY-D
MSY-GA/GE/GL	
MS-A	
MSXY-FD	

	MSC-GA-VB
	MFZ-KA/KJ
	MLZ-KA/KP
MR SLIM	PCA-A
	PCA-M
	PCA-RP
	PC-GAKD
	PCH-GAK
	PEAD-A
	PEAD-M
	PEAD-RP
	PEAD-SM/SP
	PEAD-M XX JA
	PEAD-SM XX JA
	PEAD-AAK
	PE-EAK
	PE-EAKT
	PEH-EAK
	PEH-EAKH
	PKA-A
	PKA-M
	PKA-RP
	PK-FAKLD
	PK-GAKLD
	PKH-GAKL
	PLA-A
	PLA-M
PLA-RP	

	PLA-SM
	PLA-SP
	PLA-ZM
	PLA-ZRP
	PL-BAK
	PSA-RP
	PS-GAKD
	PSH-GAK
	SE-AKLR
	SE-AKR
	SEZ-KA
	SEZ-KC
	SEZ-KD
	SEZ-M
	SL-AKLR
	SLZ-KA
	SLZ-KF
	SLZ-M
INDUSTRIAL	PEA-RP
	PEH-RP
CITY MULTI	PEFY-P-NMAU-E
	PEFY-P-NMAU-E2
	PEFY-P-NMAU-E3
	PEFY-P-NMHSU-E
	PEFY-P-NMHU-E
	PEFY-P-NMHU-E2
	PEFY-P-NMSU-ER2.TH
	PEFY-P xx VMA-E

	PEFY-P xx VMA-ER3 ¹
	PEFY-P xx VMAL-E
	PEFY-P-VMH-E
	PEFY-P xx VMH(S)-E ¹
	PEFY-P xx VMR-E ¹
	PEFY-P xx VMS1-E ¹
	PEFY-P xx VMS1-ER2 ¹
	PEFY-WP-VMA-E
	PVFY-P-E00
	PFFY-P-NEMU-E
	PFFY-P-NRMU-E
	PFFY-P xx VKM-E2 ¹
	PFFY-P xx VLRM/LEM ¹
	PFFY-P xx VLRMM-E ^{1,2}
	PFKY-P-NMBU-E2
	PFKY-P-NHMU-E2
	PFKY-P-NKMU-E2.TH
	PFKY-P-VBM.ER3
	PKFY-P xx VHM-ER2 ^{1,2}
	PKFY-P xx VKM-ER1 ^{1,2}
	PLFY-P-NBMU-ER2
	PLFY-P-NCMU-ER4.TH
	PLFY-P xx VBM-ER3 ^{1,2}
	PLFY-P XX VCM-E2 ^{1,2}
	PLFY-P xx VCM-ER2 ^{1,2}
	PLFY-P xx VEM
	PLFY-P xx VFM
	PLFY-P xx- VFM-E1

	PLFY-P xx VLDM-E ¹
	PMFY- P-NBMU-ER5
	PMFY-P xx VBM-E#2
	PMFY-P xx VBM-ER3
	PMFY-P xx VBM-ER4 ¹
	PVfy-P-E00

¹ Compatible with units manufactured since the end of 2013

² Requires PAC-IT51AD-E adaptor for CN51 connector from Mitsubishi AC unit or PAC-IT52AD-E adaptor for CN52 connector from Mitsubishi AC unit. These adaptors must be acquired through Mitsubishi Electric directly.

^{3,4} Mr Slim PEA-RP400/500GAQ and PCA-RP71/125HA/HAQ units are not compatibles.

Any air conditioner model which is not on this list, may not be compatible with the gateway.

Ingenium cannot guarantee that this document does not contain writing errors or composition errors as well as equivalent problems.